

Introduction:

During heavy acceleration or engine load, customer may experience sensation of loss in power with lack of acceleration or speed. No DTC's may occur.

**Inspection
Procedure:**

Access engine bay, apply firm pressure to the centre of the intake pipe between air box and engine assembly. If hose is found to have reduced structural integrity inspection of part number is required.

**Affected
Component
Image:**



17 November 2023

Title:

Intake Hose Collapse

Models:

02/2022 > FJA300

F33a-FTV

ENGINE

Affected Component Information:

Model	Engine	Previous Part NO.	Affected Part NO.	Part Name	QTY
Landcruiser FJA300	F33a-FTV	17881-52030	17881-52031	Intake Hose	1

Current Findings:

Trialing numerous different work arounds for the concern. Just Autos is working towards a solution for this concern in first quarter of 2024.

Field Fix Update 12/12/2023:

[Click Here for Field Fix](#)

